







a X1  WB3316S	b X1  WB3317S	c X1 	d X1 ST4×16 	e Xn  WB3317S	f X3  WB3317S
---	---	---	--	---	---

1




D	W
600	564
700	664
800	764
900	864


2




3






4




5




6



7




8



WB3317S


D	e Xn
600	2
700	2
800	2
900	3

WB3317S




Done.

WB3318S



Done.



Max 20 KG



INPUT:110V-220V 50HZ



OUTPUT:DC12V